| Honeywell BW™ Solo Replacements, Spares and Service Parts | Order Number | Price (USD) |
|------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|----------------------|
| Replacement gas label, carbon dioxide (CO ₂) | BWS-B-LABEL | \$5.00 |
| Replacement gas label, nitric oxide (NO) | BWS-N-LABEL | \$5.00 |
| Replacement gas label, phosphine (PH ₃) | BWS-P-LABEL | \$5.00 |
| Replacement gas label, hydrogen (H ₂) | BWS-R-LABEL | \$5.00 |
| Replacement gas label, sulfur dioxide (SO ₂) | BWS-S-LABEL | \$5.00 |
| Replacement gas label, chlorine dioxide (ClO ₂) | BWS-V-LABEL | \$5.00 |
| Replacement gas label, oxygen (O ₂) | BWS-X-LABEL | \$5.00 |
| Replacement gas label, hydrogen cyanide (HCN) | BWS-Z-LABEL | \$5.00 |
| Replacement gas tabet, nyurugen cyanide (11614) | DWO Z LADEL | Ψ3.00 |
| GasAlert Extreme Accessories | Order Number | Price (USD) |
| Concussion-proof boot with stainless steel alligator-style clip for GasAlert Extreme | GA-BALERT | \$56.00 |
| GasAlert Extreme Replacements, Spares and Service Parts | Order Number | Price (USD) |
| Replacement sensor screens with gasket (kit of 10) | GAXT-SS | \$34.00 |
| | GA-AG-2 | \$24.00 |
| Replacement vibration motor | GA-VM-2 | \$18.00 |
| Replacement battery - Lithium, 3V | E2829 | \$24.00 |
| Replacement breathing tubes for breathing adaptor (GA-BA-K1) | GA-BT-K1 | \$362.00 |
| Replacement front enclosure (yellow) for GasAlert Extreme | GAXT-FC1 | \$42.00 |
| Replacement front enclosure (black) for GasAlert Extreme | GAXT-FC1B | \$42.00 |
| Replacement back enclosure (yellow) with screws for GasAlert Extreme | GAXT-PC1B GAXT-BC1 | \$42.00 |
| • | | \$42.00 |
| Replacement back enclosure (black) with screws for GasAlert Extreme | GAXT-BC1B | |
| Replacement bubble label for GasAlert Extreme hydrogen sulfide (H ₂ S) | GAXT-H-BLABEL | \$8.00 |
| Replacement LCD for GasAlert Extreme | GAXT-LCD | \$17.00 |
| Replacement PCB for GasAlert Extreme ammonia (NH ₃) | GAXT-A-DL-PCB1 | \$707.00 |
| Replacement PCB for GasAlert Extreme ammonia (NH ₃), extended range | GAXT-A2-DL-PCB1 | \$675.00 |
| Replacement PCB for GasAlert Extreme carbon monoxide (CO) | GAXT-M-DL-PCB1 | \$345.00 |
| Replacement PCB for GasAlert Extreme carbon monoxide (CO-H), H ₂ resistant | GAXT-M2-DL-PCB1 | \$578.00 |
| Replacement PCB for GasAlert Extreme chlorine (Cl ₂) | GAXT-C-DL-PCB1 | \$540.00 |
| Replacement PCB for GasAlert Extreme chlorine dioxide (ClO ₂) | GAXT-V-DL-PCB1 | \$578.00 |
| Replacement PCB for GasAlert Extreme ethylene oxide (ETO) | GAXT-E-DL-PCB1 | \$780.00 |
| Replacement PCB for GasAlert Extreme hydrogen sulfide (H ₂ S) | GAXT-H-DL-PCB1 | \$345.00 |
| Replacement PCB for GasAlert Extreme hydrogen sulfide (H ₂ S), extended range | GAXT-H-2-DL-PCB1 | \$410.00 |
| Replacement PCB for GasAlert Extreme hyrdogen cyanide (HCN) | GAXT-Z-DL-PCB1 | \$522.00 |
| Replacement PCB for GasAlert Extreme nitric oxide (NO) | GAXT-N-DL-PCB1 | \$578.00 |
| Replacement PCB for GasAlert Extreme nitrogen dioxide (NO ₂) | GAXT-D-DL-PCB1 | \$571.00 |
| Replacement PCB for GasAlert Extreme oxygen (O ₂) | GAXT-X-DL-PCB1 | \$362.00 |
| Replacement PCB for GasAlert Extreme oxygen(O ₂) | GAXT-G-DL-PCB1 | \$1,018.00 |
| 1 | | |
| Replacement PCB for GasAlert Extreme phosphine (PH ₃) Replacement PCB for GasAlert Extreme sulfur dioxide (SO ₂) | GAXT-P-DL-PCB1 GAXT-S-DL-PCB1 | \$578.00 \$578.00 |
| Replacement PCB for Gasalert Extreme sulfur dioxide (50 ₂) | GAV1-2-DF-bCB1 | \$316.00 |
| FoxiPro® Replacements, Spares and Service Parts | Order Number | Price (USD) |
| Replacement sensor filter kit | 54-46-101 | \$9.00 |
| est cap without hose | 54-46-106 | \$20.00 |
| Replacement carbon monoxide (CO) sensor for ToxiPro | 54-47-01 | \$419.00 |
| Replacement hydrogen sulfide (H ₂ S) sensor for ToxiPro | 54-47-02 | \$419.00 |
| Replacement sulfur dioxide (SO ₂) sensor Note: 1 year warranty. | 54-47-03 | \$653.00 |
| Replacement phosphine (PH ₃) sensor | 54-47-13 | \$653.00 |
| Note: 1 year warranty. | 5 · · · · 20 | , , , , , , |
| Replacement chlorine (Cl ₂) sensor Note: 1 year warranty. | 54-47-18 | \$653.00 |
| Replacement carbon monoxide sensor (CO-H), H ₂ resistant | 54-47-19 | \$486.00 |
| Replacement chlorine dioxide (ClO ₂) sensor Note: 1 year warranty. | 54-47-20 | \$737.00 |
| Replacement ammonia (NH ₃) sensor Note: 1 year warranty. | 54-47-21 | \$653.00 |
| Replacement hydrogen cyanide (HCN) sensor | 54-47-23 | \$737.00 |
| Note: 1 year warranty. Replacement nitrogen dioxide (NO ₂) sensor | 54-47-24 | \$698.00 |
| Note: 1 year warranty. | | |
| Replacement oxygen (O ₂) sensor for ToxiPro | 54-47-90 | \$308.00 |
| Replacement alligator clip | TP-AG-1 | \$49.00 |
| | | |

5062-33-USD-EN **77**